

07-02-08  
Straw Barrier Project  
Snowball Waste Rock  
Completed Project

M0370012  
to file  
No task

**Picture 1**

**Straw bales  
installed at toe  
of snowball  
waste rock area.**



**Picture 2**

**Straw bales  
installed at toe  
of snowball  
waste rock area.**



**Picture 3**

**Straw bales  
installed at toe  
of snowball  
waste rock area.**



**Picture 4**

**Straw bales  
installed at toe  
of snowball  
waste rock area.**

